


BC0314

Engine: **TOYOTA 2JZGE non VVTi**

Advertised Duration:	int 264°	<u>ехн</u> 264°
Duration @ .050":	220°	226°
Valve Lift (inches):	.375"	.375"
Valve Lift (mm):	9.52	9.52
Valve Lash (inches):	.006"	.008"

Recommended Valve Spring/Titanium Retainer Kit: **BC0300**

WARNING: Due to various cam gear thicknesses, make sure cam bolt does not bottom out in the cam threads. Clearance cam bolt length if necessary. Failure to check may cause engine damage.



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty.

Not legal for sale or use on emission controlled motor vehicles.






BC0314

Engine:	TOYOTA 2JZGE non VVTi

Advertised Duration:	int 264°	<u>ехн</u> 264°
Duration @ .050":	220°	226°
Valve Lift (inches):	.375"	.375"
Valve Lift (mm):	9.52	9.52
Valve Lash (inches):	.006"	.008"

Recommended Valve Spring/Titanium Retainer Kit: **BC0300**

WARNING: Due to various cam gear thicknesses, make sure cam bolt does not bottom out in the cam threads. Clearance cam bolt length if necessary. Failure to check may cause engine damage.



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty

Not legal for sale or use on emission controlled motor vehicles.

