


## BC0047-2 8620 STEEL BILLET CORE

Engine: **HONDA-ACURA K20A2/Z3 IVTEC** 

Advertised Duration:	1 <u>INT</u> 330°	330°
Duration @ .050" (@ Lobe):	258°	258°
Duration @ .050" (@ Valve):	276°	276°
Valve Lift (inches):	.570"	.516"
Valve Lift (mm):	14.50	13.11
Valve Lash (inches):	.010"	.012"

Recommended Valve Spring/Titanium Retainer Kit: **BC0040T** 



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty.

Not legal for sale or use on emission controlled motor vehicles.






## BC0047-2 8620 STEEL BILLET CORE

Engine: **HONDA-ACURA K20A2/Z3 iVTEC** 

Advertised Duration:	<u>int</u> 330°	330°
Duration @ .050" (@ Lobe):	258°	258°
Duration @ .050" (@ Valve):	276°	276°
Valve Lift (inches):	.570"	.516"
Valve Lift (mm):	14.50	13.11
Valve Lash (inches):	.010"	.012"

Recommended Valve Spring/Titanium Retainer Kit: **BC0040T** 



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty.

Not legal for sale or use on emission controlled motor vehicles.

