


## BC0056 8620 STEEL BILLET CORE - 1 LOBE

Engine: **HONDA-ACURA K20A2/Z3 IVTEC** 

Advertised Duration:	<u>int</u> 320°	336°
Duration @ .050" (@ Lobe):	250°	262°
Duration @ .050" (@ Valve):	268°	280°
Valve Lift (inches):	.598"	.560"
Valve Lift (mm):	15.19	14.22
Valve Lash (inches):	.008"	.010"

Recommended Valve Spring/Titanium Retainer Kit: **BC0040T** 



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty.

Not legal for sale or use on emission controlled motor vehicles.






## BC0056 8620 STEEL BILLET CORE - 1 LOBE

Engine: **HONDA-ACURA K20A2/Z3 iVTEC** 

Advertised Duration:	1 <u>INT</u> 320°	<del>ехн</del> 336°
Duration @ .050" (@ Lobe):	250°	262°
Duration @ .050" (@ Valve):	268°	280°
Valve Lift (inches):	.598"	.560"
Valve Lift (mm):	15.19	14.22
Valve Lash (inches):	.008"	.010"

Recommended Valve Spring/Titanium Retainer Kit: **BC0040T** 



Camshafts damaged by improper installation, excessive spring pressure, valve train bind or retainers contacting valve guides or seals are void from warranty.

Not legal for sale or use on emission controlled motor vehicles.

